


RIVER MILE 10.9 REMOVAL ACTION CAPPING OPERATIONS WEEKLY STATUS REPORT

Summary of capping operations through week ending April 27, 2014


As of April 27, 100% of the dredged and capped area has been protected with a fabric and stone armoring layer. Application of a habitat layer over the armor stone is expected to be completed by mid-May, 2014. The attached figure shows the section of RM 10.9 where the fabric and stone has been placed to date.


All capping operations were conducted within acceptable water quality monitoring limits. Monitoring buoys #1 and #4 experienced calibration problems on 4/24/14 that were corrected by 4/25/14.

Capping Progress to Date Shown in Blue



Real-Time Water Quality Monitoring





Water Quality Monitoring Locations